

AGILITY / iPATH FIRMWARE COMPATIBILITY CHART

iPATH	AGILITY	ACR1000A	ACR1000A-R2	ACR500DP-T	ACR1002A	ACR1020A	ACR1012A	COMMENT
NA	1.0	•						Point to Point Only
NA	1.3	•						Point to Point Only
NA	1.4	•						Point to Point Only
1.0	1.8	•						Beta iPath
1.2	1.9	•						Original iPath Hardware
1.3	1.9	•						
1.4	1.9	•						
1.5	1.9	•						
1.6	1.1	•						
1.8	1.1	•						
2.0	2.1				•			
2.0	2.2	•						
2.1	2.3				•			
2.1	2.4				•			
2.2	2.6				•			
2.3	2.7	•			•		•	
2.4	2.8	•			•		•	
2.5	2.9	•			•		•	
3.0	3.0	•			•		•	
3.1	3.1	•			•		•	
3.3	3.3	•	•		•		•	Intro of TLS Encryption
3.3	3.4					•		
3.3	3.5	•	•		•	•	•	
3.3	3.6	•	•		•	•	•	
3.3	3.7	•	•		•	•	•	
3.5	3.7	•	•		•	•	•	
4.0	3.3	•	•		•	•	•	New IU iPath Hardware
4.0	3.5	•	•		•	•	•	
4.0	3.6	•	•		•	•	•	
4.0	3.7	•	•		•	•	•	*
4.1	4.1		•		•	•	•	Introduction of DHCP
4.2	4.2		•		•	•	•	
4.3	4.3		•		•	•	•	
4.4	4.4		•		•	•	•	ECC Change
4.5	4.5		•		•	•	•	
4.6	4.5		•		•	•	•	
4.6	4.6		•		•	•	•	
4.7	4.5		•		•	•	•	
4.7	4.6		•	•	•	•	•	
4.8	4.8		•	•	•	•	•	

* ECC CHANGE. CANNOT REVERT FIRMWARE

NOTE: ACR1000A is no longer supported beyond iPath F/W version 4.0. ECC (Error Correcting Code) change means that after upgrading to this version, it is no longer possible to revert to an older firmware version.

